



6394414

Pleasant Prairie Logistics
Brokered To: PPL-Cold Iron
CustomerCare@PPLdelivers.com

28523705

107 - HEBER, CA

Form containing delivery details: DELIVER TO: KENWORTH SALES COMPANY, PICK UP FROM: ACTIVE USA, INC., LOAD/TRIP: 1899827, TERM: 107, LOAD TYPE: 3W, POSITION: 1, SHIP DATE: 03/01/2023, ETA: 03/04/2023, VIN: 3WKZD40X7RF330976, DRIVER NAME, COLOR: WHITE, MODEL: T880 Series Converter, HOME TERM: 001, TRACTOR, TRAILER, ROUTED MILES: 734, DRIVER: INITIAL BOXES CORRESPONDING WITH EQUIPMENT & BAG SEAL NUMBERS, Plant Fuel Inches, DEF, R 0.00 L 0.00 Plant 0 Delivery

AREA CODES

- 29 Air Bag/Pedestal
69 Air Cleaner
64 Air Deflector/Fairing Roof
09 Air Tanks
01 Antenna
84 Axle Shafts
07 Battery Box and Cover
03 Bumper
57 Bunk/Sleeper Curtain
74 Cab Panel, Front
75 Cab Panel, Left
77 Cab Panel, Rear
76 Cab Panel, Right
21 Cabinetry Interior
67 Carpet, Floor Mat
80 Cowl
66 Dashboard/Instrument Panel
49 Deck Plate
23 DEF Tank
10 Door, Left
05 Door, Right
63 Door Panel Interior, Left
62 Door Panel Interior, Right
72 Drive Shaft
91 Exhaust/Stack
14 Fender, Left Front
16 Fender, Right Front
86 5th Wheel
70 Fog Lamps
90 Frame
04 Fuel Tank Fairing, Left
11 Fuel Tank Fairing Right
81 Fuel Tank, Left
89 Fuel Tank, Right
51 Glass, Left
82 Glass, Rear
58 Glass, Right
22 Grill
24 Headlight and Rim, Left
25 Headlight and Rim, Right
19 Headliner
27 Hood Panel, Top
68 Hood Vertical Panel, Left
38 Hood Vertical Panel, Right
53 Horn, Right/Left
15 Keys/Key Fob
59 Leveling Valve Suspension
47 Light Cable
65 Marker Lamps
18 Mattress
30 Mirror Outside, Left
31 Mirror, Outside Right
45 Mirror, Spot Left
71 Mirror, Spot Right
73 Mud Flap, Right/Left
28 Muffler
12 Muffler Shield
97 Oil Pan
98 Other
17 Quarter Fender, Right/Left
33 Radio, CD Player, CB
37 Roof Panel, Cab
56 Roof Panel, Sleeper
94 Seat, Left
95 Seat, Right
06 Side Extender, Left
39 Side Extender, Right
48 Sleeper Compartment, Interior
83 Sleeper Panel, Left
13 Sleeper Panel, Rear
36 Sleeper Panel, Right
79 Steering Wheel Interior
08 Step Assembly, Left
42 Step Assembly, Right
93 Suspension - Undercarriage
46 Tail Lamp, Right/Left
02 Tires - Forward Tandem
85 Tires - Rear Tandem
43 Tires - Steer Axle
60 Tow Hook, Detachable
55 Trailer Hoses
52 Turn Signal, Left
35 Turn Signal, Right
26 Winter Front/BugScreen
78 Visor, Exterior Sun
87 Wheels - Forward Tandem
96 Wheels - Rear Tandem
92 Wheels - Steer Axle
20 Windshield Glass

TYPE CODES - USE TO DESCRIBE CONDITION

- 01 BENT
02 BROKEN
03 CUT
04 DENTED
05 CHIPPED
06 CRACKED
07 GOUGED
08 MISSING
09 SCUFFED
10 STAINED or SOILED
11 PUNCTURED
12 SCRATCHED
13 TORN
14 LEAKING

SEVERITY CODES - USE TO SPECIFY SIZE OF DAMAGE

- 1 Up To and Including 1" Length/Diameter
2 Over 1" Up To and Including 3" Length/Diameter
3 Over 3" Up To and Including 6" Length/Diameter
4 Over 6" Up To and Including 12" Length/Diameter
5 Over 12" Length/Diameter
6 Missing

DRIVER REVIEW CODES

- OK Agree with exception
LS Less severe than noted
NT Not transportation
CA Commercially acceptable
UL Unable to locate

INSTRUCTIONS: Enter Damage Codes for Area, Type, Severity and Driver Review

This form to be used for recording TRANSPORTATION RELATED DAMAGE ONLY.

Table for recording damage with columns: Area, Type, Severity, Driver Review, Cause (Office Use Only)

COMMENTS:

DEALER - Please CIRCLE the appropriate answer for the following questions:

Form with questions: All hang on wiring removed, all connections returned to original condition, all lights operational? All temporary fenders, frame blocks, banding, saddles, etc., disposed of or made ready for return shipment? Axle shafts reinstalled correctly, all grease leakage removed? Spring parking brakes returned to correct position with dust covers? Any items removed such as antennas, stack extensions, tail lights, etc., reinstalled correctly?

SIGNED RECEIPT REQUIRED

DELIVERY RECEIPT-CORP. CLAIMS

Terminal Manager Signature

Date

Corrective Action Taken (Circle): None Reprimand Training



6409240

Pleasant Prairie Logistics
Brokered To: PPL-Cold Iron
CustomerCare@PPLdelivers.com

28523705

107 - HEBER, CA

DELIVER TO: 800-222-7831 PICK UP FROM: ACTIVE USA, INC. 425 E HEBER RD HEBER, CA 92249
LOAD/TRIP 1899827 28523705 TERM. 107 LOAD TYPE 3W POSITION 2
SHIP DATE 03/01/2023 ETA 03/04/2023
SPECIAL INSTRUCTIONS 800-222-7831 RCVG M-F 8A-4:30P, FOR WEEKENDS CALL 877-845-7933 SVC//24HR ADV CALL/ELECTRIC HOIST.PW
VIN 3WKZP4EX2RF330349 DRIVER NAME
COLOR WHITE MODEL T880 Series Converter HOME TERM 001 TRACTOR TRAILER
ROUTED MILES 734
DRIVER: INITIAL BOXES CORRESPONDING WITH EQUIPMENT & BAG SEAL NUMBERS
90-18-12892 90-22-01646 Plant Fuel Inches DEF R 0.00 L 0.00 Plant 0 Delivery

AREA CODES

- 29 Air Bag/Pedestal 23 DEF Tank 58 Glass, Right 73 Mud Flap, Right/Left 08 Step Assembly, Left
69 Air Cleaner 10 Door, Left 22 Grill 28 Muffler 42 Step Assembly, Right
64 Air Deflector/Fairing Roof 05 Door, Right 24 Headlight and Rim, Left 12 Muffler Shield 93 Suspension - Undercarriage
09 Air Tanks 63 Door Panel Interior, Left 25 Headlight and Rim, Right 97 Oil Pan 46 Tail Lamp, Right/Left
01 Antenna 62 Door Panel Interior, Right 19 Headliner 98 Other 02 Tires - Forward Tandem
84 Axle Shafts 72 Drive Shaft 27 Hood Panel, Top 17 Quarter Fender, Right/Left 85 Tires - Rear Tandem
07 Battery Box and Cover 91 Exhaust/Stack 68 Hood Vertical Panel, Left 33 Radio, CD Player, CB 43 Tires - Steer Axle
03 Bumper 14 Fender, Left Front 38 Hood Vertical Panel, Right 37 Roof Panel, Cab 60 Tow Hook, Detachable
57 Bunk/Sleeper Curtain 16 Fender, Right Front 53 Horn, Right/Left 56 Roof Panel, Sleeper 55 Trailer Hoses
74 Cab Panel, Front 86 5th Wheel 15 Keys/Key Fob 94 Seat, Left 52 Turn Signal, Left
75 Cab Panel, Left 70 Fog Lamps 59 Leveling Valve Suspension 95 Seat, Right 35 Turn Signal, Right
77 Cab Panel, Rear 90 Frame 47 Light Cable 06 Side Extender, Left 26 Winter Front/BugScreen
76 Cab Panel, Right 04 Fuel Tank Fairing, Left 65 Marker Lamps 39 Side Extender, Right 78 Visor, Exterior Sun
21 Cabinetry Interior 11 Fuel Tank Fairing Right 18 Mattress 48 Sleeper Compartment, Interior 87 Wheels - Forward Tandem
67 Carpet, Floor Mat 81 Fuel Tank, Left 30 Mirror Outside, Left 83 Sleeper Panel, Left 96 Wheels - Rear Tandem
80 Cowl 89 Fuel Tank, Right 31 Mirror, Outside Right 13 Sleeper Panel, Rear 92 Wheels - Steer Axle
66 Dashboard/Instrument Panel 51 Glass, Left 45 Mirror, Spot Left 36 Sleeper Panel, Right 20 Windshield Glass
49 Deck Plate 82 Glass, Rear 71 Mirror, Spot Right 79 Steering Wheel Interior

TYPE CODES - USE TO DESCRIBE CONDITION

- 01 BENT 06 CRACKED 11 PUNCTURED
02 BROKEN 07 GOUGED 12 SCRATCHED
03 CUT 08 MISSING 13 TORN
04 DENTED 09 SCUFFED 14 LEAKING
05 CHIPPED 10 STAINED or SOILED

SEVERITY CODES - USE TO SPECIFY SIZE OF DAMAGE

- 1 Up To and Including 1" Length/Diameter
2 Over 1" Up To and Including 3" Length/Diameter
3 Over 3" Up To and Including 6" Length/Diameter
4 Over 6" Up To and Including 12" Length/Diameter
5 Over 12" Length/Diameter
6 Missing

DRIVER REVIEW CODES

- OK Agree with exception
LS Less severe than noted
NT Not transportation
CA Commercially acceptable
UL Unable to locate

INSTRUCTIONS: Enter Damage Codes for Area, Type, Severity and Driver Review

This form to be used for recording TRANSPORTATION RELATED DAMAGE ONLY.

Table with 10 columns: Area, Type, Severity, Driver Review, Cause (Office Use Only). Repeated 4 times.

COMMENTS:

DEALER - Please CIRCLE the appropriate answer for the following questions:

Table with 5 columns of questions regarding wiring, temporary fenders, axle shafts, spring parking brakes, and removed items.

CONSIGNEE: SIGNATURE BELOW ACKNOWLEDGES THE RECEIPT OF TRUCKS, EQUIPMENT AND BAGS (SEALED) AS INDICATED ABOVE AND THAT THE UNDECKING AREA HAS BEEN POLICED, EQUIPMENT AND BAGS PROPERLY STORED.

DEALER SIGNATURE DATE TIME A.M. P.M. DRIVER SIGNATURE

SIGNED RECEIPT REQUIRED DELIVERY RECEIPT-CORP. CLAIMS



6356758

Pleasant Prairie Logistics
Brokered To: PPL-Cold Iron
CustomerCare@PPLdelivers.com

28523705

107 - HEBER, CA

DELIVER TO: 800-222-7831 PICK UP FROM: ACTIVE USA, INC.
LOAD/TRIP 1899827 TERM. 107 LOAD TYPE 3W POSITION 3
SHIP DATE 03/01/2023 ETA 03/04/2023
SPECIAL INSTRUCTIONS 800-222-7831
VIN 3BKZL49X0RF314371 DRIVER NAME
COLOR DK AQUA MODEL T880 Series Converter HOME TERM 001 TRACTOR TRAILER
ROUTED MILES 734
DRIVER: INITIAL BOXES CORRESPONDING WITH EQUIPMENT & BAG SEAL NUMBERS
90-18-12892 90-22-01646 Plant Fuel Inches DEF R 0.00 L 0.00 Plant 0 Delivery

AREA CODES

- 29 Air Bag/Pedestal
69 Air Cleaner
64 Air Deflector/Fairing Roof
09 Air Tanks
01 Antenna
84 Axle Shafts
07 Battery Box and Cover
03 Bumper
57 Bunk/Sleeper Curtain
74 Cab Panel, Front
75 Cab Panel, Left
77 Cab Panel, Rear
76 Cab Panel, Right
21 Cabinetry Interior
67 Carpet, Floor Mat
80 Cowl
66 Dashboard/Instrument Panel
49 Deck Plate
23 DEF Tank
10 Door, Left
05 Door, Right
63 Door Panel Interior, Left
62 Door Panel Interior, Right
72 Drive Shaft
91 Exhaust/Stack
14 Fender, Left Front
16 Fender, Right Front
86 5th Wheel
70 Fog Lamps
90 Frame
04 Fuel Tank Fairing, Left
11 Fuel Tank Fairing Right
81 Fuel Tank, Left
89 Fuel Tank, Right
51 Glass, Left
82 Glass, Rear

- 58 Glass, Right
22 Grill
24 Headlight and Rim, Left
25 Headlight and Rim, Right
19 Headliner
27 Hood Panel, Top
68 Hood Vertical Panel, Left
38 Hood Vertical Panel, Right
53 Horn, Right/Left
15 Keys/Key Fob
59 Leveling Valve Suspension
47 Light Cable
65 Marker Lamps
18 Mattress
30 Mirror Outside, Left
31 Mirror, Outside Right
45 Mirror, Spot Left
71 Mirror, Spot Right

- 73 Mud Flap, Right/Left
28 Muffler
12 Muffler Shield
97 Oil Pan
98 Other
17 Quarter Fender, Right/Left
33 Radio, CD Player, CB
37 Roof Panel, Cab
56 Roof Panel, Sleeper
94 Seat, Left
95 Seat, Right
06 Side Extender, Left
39 Side Extender, Right
48 Sleeper Compartment, Interior
83 Sleeper Panel, Left
13 Sleeper Panel, Rear
36 Sleeper Panel, Right
79 Steering Wheel Interior

- 08 Step Assembly, Left
42 Step Assembly, Right
93 Suspension - Undercarriage
46 Tail Lamp, Right/Left
02 Tires - Forward Tandem
85 Tires - Rear Tandem
43 Tires - Steer Axle
60 Tow Hook, Detachable
55 Trailer Hoses
52 Turn Signal, Left
35 Turn Signal, Right
26 Winter Front/BugScreen
78 Visor, Exterior Sun
87 Wheels - Forward Tandem
96 Wheels - Rear Tandem
92 Wheels - Steer Axle
20 Windshield Glass

TYPE CODES - USE TO DESCRIBE CONDITION

- 01 BENT
02 BROKEN
03 CUT
04 DENTED
05 CHIPPED
06 CRACKED
07 GOUGED
08 MISSING
09 SCUFFED
10 STAINED or SOILED
11 PUNCTURED
12 SCRATCHED
13 TORN
14 LEAKING

SEVERITY CODES - USE TO SPECIFY SIZE OF DAMAGE

- 1 Up To and Including 1" Length/Diameter
2 Over 1" Up To and Including 3" Length/Diameter
3 Over 3" Up To and Including 6" Length/Diameter
4 Over 6" Up To and Including 12" Length/Diameter
5 Over 12" Length/Diameter
6 Missing

DRIVER REVIEW CODES

- OK Agree with exception
LS Less severe than noted
NT Not transportation
CA Commercially acceptable
UL Unable to locate

INSTRUCTIONS: Enter Damage Codes for Area, Type, Severity and Driver Review

This form to be used for recording TRANSPORTATION RELATED DAMAGE ONLY.

Table with columns for Area, Type, Severity, Driver Review, and Cause (Office Use Only). Multiple rows for recording damage.

COMMENTS:

DEALER - Please CIRCLE the appropriate answer for the following questions:

Table with 4 columns of questions regarding wiring, fenders, axle shafts, and parking brakes, with YES/NO options.

CONSIGNEE: SIGNATURE BELOW ACKNOWLEDGES THE RECEIPT OF TRUCKS, EQUIPMENT AND BAGS (SEALED) AS INDICATED ABOVE AND THAT THE UNDECKING AREA HAS BEEN POLICED, EQUIPMENT AND BAGS PROPERLY STORED.

DEALER SIGNATURE DATE TIME A.M. P.M. DRIVER SIGNATURE

SIGNED RECEIPT REQUIRED

DELIVERY RECEIPT-CORP. CLAIMS